

A




Höyryhansikas

B




Toimitamme **vastuksia** kaikkiin koneisiin suoraan varastosta tai toimitusajalla

C



Raudan mikrot

D




Erlaisia termostaatteja

E



Kevennin esim. höyryrautaan tai tahranoistopistooliin

F



Puhdistusharjat

G

190°F 88°C	190°F 88°C
200°F 93°C	200°F 93°C
210°F 99°C	210°F 99°C
220°F 104°C	220°F 104°C
230°F 110°C	230°F 110°C

H

1	2	3	4
100°F 37.8°C	140°F 60°C	190°F 88°C	240°F 116°C
105°F 40.6°C	150°F 65.6°C	200°F 93°C	250°F 121°C
110°F 43.3°C	160°F 71°C	210°F 99°C	260°F 127°C
120°F 47°C	170°F 77°C	220°F 104°C	270°F 132°C
130°F 54.4°C	180°F 82°C	230°F 110°C	280°F 138°C

5	6	7	8
290°F 143°C	340°F 171°C	390°F 199°C	450°F 232°C
300°F 149°C	350°F 177°C	400°F 204°C	465°F 241°C
310°F 154°C	360°F 182°C	410°F 210°C	480°F 249°C
320°F 160°C	370°F 188°C	420°F 216°C	490°F 254°C
330°F 166°C	380°F 193°C	435°F 224°C	500°F 260°C

Lämmönmittaukseen tarkoitetut liuskat
37,8° - 260° C